

1. Product Name(s) and Parts Number(s)

NOVASTACK 35-P PLUG ASS'Y: 20708-0**E-##

2. Packing Material

Pos.	EMBOSS TAPE		REEL		PACKING CARTON
	TAPE WIDTH	THICKNESS	DIAMETER	WIDTH	
10~ 14P	12.0	1.10	Φ380	17.4	386×386×200 OUTER
16~ 38P	16.0			21.4	
40~ 70P	24.0			29.4	

3. Packing Quantity

Pos	QTY. IN EMBOSS TAPE (1 REEL)	QTY. IN PACKING CARTON (1 CARTON)
10~ 14P	20,000	20,000×9=180,000 (9 REELS)
16~ 38P		20,000×7=140,000 (7 REELS)
40~ 70P		20,000×5=100,000 (5 REELS)

4. Packing Label

Put a label on the designated place of the each reels and Packing CARTON.

The diagram shows a rectangular packing label divided into several sections. On the left, there are fields for 'P/N', 'QTY', and 'LOT'. Below these is a QR code. The middle section contains 'NAME:' and 'MADE IN *****'. The right section contains 'CHECK' and 'REMARK'. To the right of the label are three recycling symbols: '06 PS' (labeled 8), '01 PET' (labeled 9), and '06 PS' (labeled 10). A 'RoHS Compliant' logo and an 'HF' logo are also present.

- ① Part Number
- ② Quantity
- ③ Ten Digits Product Lot Number

Y	Y	M	M	D	D	#	#	#	#
Year		Month		Day		Four Digit Code for I-PEX usage			

- ④ Product Name : NOVASTACK 35-P PLUG ASS'Y **P
- ⑤ QR Code
- ⑥ Check Stamp
- ⑦ Country of Origin
- ⑧ Recycle Mark and Compliance Mark
- ⑨ Logo Mark
- ⑩ Manufacture Name

5. Packing Method

5-1. Put a packing label on the designated place of reel as shown Fig.1.




Fig. 1

5-2. Packing of Packing Carton [See Fig.2.]

Put a packing label on the designated place of packing carton as shown Fig.2.




Fig. 2